

TIMING GEAR BACKLASH

Engine Types 1600, 1600 S, and 1600 S-90

Installation tolerance (new) for backlash between the timing gear and crankshaft gear has been changed to 0.015 - 0.025 mm (.0006 to .0010 in.). This tolerance must be maintained when repairing any engine with the 3-piece crankcase.